

Please double check the C-C spacing on your sponson dowel mounts. The spacing below is set at 19.0 mm (.748") - thats very close to 3/4" (.75").

